How to use a Hand Liester





Ensure Leister is plugged in. Hold bottom button pressed Turn dial to desired temperature. in till you hear it turn on.





how to use roller while welding.



Check weld. To turn off Liester press and hold bottom dial until a snowflake appears on the display. Wait for cooldown.



Place Liester away from everything it will turn off after the cooldown ends.