
How to deploy a foam-wall berm









Slide the logs into the pockets. Access points approximately every 10 feet. Should finish like the picture.